

# ELECTRONICS TESTING CENTER TAIWAN

No.8, LANE 29, WENMING ROAD, LOSHAN TSUN  
KWEISHAN HSIANG, TAOYUAN, TAIWAN, R.O.C.  
PHONE : (03) 3280026 · FAX : (03) 3276175

REF. No.: ET94A-11-023

Sheet : 1 of 5 Sheets

ISSUED DATE : NOV 14,2005

1. Applicant Name : CES Audio Inc.  
Address : No.31-1,Lane 112,Su Wei Road , Panchiao , Taipei ,  
Taiwan,220
2. Description of Device : Sound Projector  
Model No. : SOP-5200D (1 set)  
Date of Receipt : NOV 08,2005
3. Date of Measurement : NOV 11,2005
4. Test Specification : According to Applicant's Spec.  
(IEC60529 Edition 2.1 2001-02)
5. Test Items : See the following sheets
6. Test Condition & Result : See the following sheets

The test results relate only to the items tested.

The report shall not be reproduced except in full without the written approval of Electronics Testing Center, Taiwan.

This inspection has carried out to the best of our knowledge and ability, and our responsibility is limited to the exercise of reasonable care, this certification is not intended to believe the sellers from their contractual obligations.

Tested by : Ricky Huang  
Ricky Huang  
Engineer of  
Product Safety Testing  
Department

Checked by : Henry Cheng  
Henry Cheng  
Section Manager of  
Product Safety Testing  
Department



# ELECTRONICS TESTING CENTER TAIWAN

REF. No.: ET94A-11-023

Sheet : 2 of 5 Sheets

一、Test Item: IP66

二、Test Condition:

1. IPX6 :

- (1) Internal diameter of the nozzle: 12.5 mm.
- (2) Delivery rate: 100 l/min  $\pm 5\%$ .
- (3) Distance from nozzle to enclosure surface: between 2.5 m and 3 m.
- (4) The duration of test is 3 min.

2. IP6X :

- (1) Maximum depression of 2kPa(20mbar).
- (2) The total duration of test is 8 hr.

三、Test Results:

Request/Experiment	Results	Remark
After testing in accordance with appropriate requirements of IEC60529 14.2.6 the enclosure shall be inspected for ingress of water	No ingress of water was found inside.	IPX6

Request/Experiment	Results	Remark
After testing in accordance with appropriate requirements of IEC60529 13.4 and 13.6 the enclosure shall be inspected for ingress of dust.	No ingress of dust was found inside.	IP6X

# ELECTRONICS TESTING CENTER TAIWAN

REF. No.: ET94A-11-023

Sheet : 3 of 5 Sheets

MODEL No : SOP-5200D



IPX6 Test




# ELECTRONICS TESTING CENTER TAIWAN

REF. No.: ET94A-11-023

Sheet : 4 of 5 Sheets

No ingress of water was found inside



IP6X Test



# ELECTRONICS TESTING CENTER TAIWAN

REF. No.: ET94A-11-023

Sheet : 5 of 5 Sheets

No ingress of dust was found inside

